

Reg.-No.: **K-15038/25**  
Eventdate: **12-13 April 2025**

Status of the event : **International / National A**  
from **The Chief Scrutineer**  
to: **Timekeeping and Racecontrol**

## **RMC Germany Round 2**

### **Wackersdorf**

### **Reporting Frontfairing**

**Class: DD2**

**Session: Heat 1**

**Penalty Qualifying: A drop down of 5 positions**  
**(DMSB-Kart-Reglement 2025, Art. B.17 b)**

**Penalty Heats, Superheats, Final: Time penalty 5 sec.**  
**DMSB-Kart-Reglement 2025, Art. B.17 b)**

## **Involved Competitors**

**Below competitors with "Front Fairing" not in correct position**

**408, 480, 448, 420, 440, 418**

Note: In application of article B.17.b) DMSB Karting Regulations, possible remedies against the penalty imposed by the Clerk of the Course or Race Director are limited (This decisions are not subject to Protest or Appeal). In addition to this part of DMSB Kart Regulations, against an imposed penalty (5s time penalty or drop of 5 positionen in QP) for incorrect position of front fairing or incorrect mounted front fairing no protest or appeal is permitted (art. B.19 DMSB Karting Regulations or art. 2.3.3 CIK-FIA Karting General Prescriptions).

Place: **Wackersdorf**

Date: **12.04.2025**

Time: **13:39:15**

Cief Scrutineer: **Martin Lainer**